



Notes:

1. Low gradient close to the coast
2. Uniform steep gradient over Southlands
3. Very high recharge indicated in the e
4. Steep gradient crossing lake indicate that groundwater and the lake are not connected!

Only 12 monitoring points indicated on original.